

GNX G604.08.13kX Release Notes

OVERVIEW

DATE ISSUED:	November 15, 2020
ISSUED BY:	Sierra Wireless GNX Product Management
PRODUCTS AFFECTED:	All GNX-6 LTE and GNX-5P LTE devices
FOR DISTRIBUTION TO:	All GNX Customers
SUMMARY:	<p>The major features for this release are:</p> <ul style="list-style-type: none">• Adds Support for modem response parsing and modem power up. Ported from 9.02. MODEMFOTA and LARA-R202.• Adds "Itemobile.apn" to the APN huntlist for Rogers.• Fix for GNX not properly detecting J1939 zero DTC in G604_08_09kX and later.• Fix for handle of END_ROM_ADDR section, includes Companion PRI.• Improvement for GNX reporting momentary invalid ECM odometer value close to ignition on/off.• Creates a label to indicate if the executing firmware is an official release or a pre-release.• Fix for GNX-5P incorrectly reporting 4 relay output.• Fix for Fleet Complete APN name in Mexico, make APN check case-agnostic.

PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE:	For products in the field this update is available now
---------------------------------------	--

CONTACT

SUPPORT:	support@sierrawireless.com
-----------------	----------------------------

REVISION HISTORY

15-NOV-2020	Initial Release
--------------------	-----------------